



CONCEPTION AND MAIN APPLICATIONS

These jig saws are designed to be used for light work.

Their brief benefits are;

*Least vibration among same class models


*More comfortable

by large trigger switch, slidable dust cover and positive stop at 45 bevel cut

*Chip/sawdust can be collected

by connecting to vacuum cleaner

Model	Variable speed	Jig Saw Blade
4322	No	B-type
4323	Yes	B-type
4322M	No	Makita-type
4323M	Yes	Makita-type



► Specifications

Voltage (V) Current (A)	Cycle (Hz)	Continuous Rating (W)		Max Output(W)	
		Input	Output	Max. Output(W)	
100	4.2	50/60	400	225	380
120	3.7	50/60	400	225	380
220	1.9	50/60	400	225	380
230	1.8	50/60	400	225	380
240	1.8	50/60	400	225	380

Strokes per minute		4322/4322M	3100spm
		4323/4323M	500 - 3100spm
Max.cutting	Wood	4322/4323	65mm(2-9/16")
capacities		4322M/4323M	40mm(1-9/16")
	Soft steel		6mm(1/4")
Net weight			18Kg(4.01bs)
Cord length		2.0m(6.6ft)	

► Standard equipment

Jig Saw Blade B-10 ----- 1 pc. (4322/4323) Jig Saw Blade No.10----- 1pc. (4322M/4323M)

Hex. Wrench 3----- 1pc.

Note>The standard equipment may differ from country to country.

Optional accessories

Guide Rule Set

Kerf Board

Hose Complete 28-1.5


Hose Complete 28-3.0

Jig Saw Blade No.51, SB, 59, B-10-19, B-21-27, B-16L, BR-13 (4322/4323)


Jig Saw Blade No.1-5,8-10, 16, 17,41,42,BR-3 (4322M/4323M)

► Repair


When assembling the housings R/L, securely insert the O ring into the deepest of the housing while using care not to drop the O ring at housing R side.




Use care that the polyurethane sponge seal may not be caught in when assembling the housing R/L.



Cautions in replacing the field : Set the field on the housing L in a direction shown on the below figure. <Low Voltage Motor>




<High Voltage Motor>




► Circuit drawing


<4322, M434> [Low Voltage]




[High Voltage]



<4323> [Low Voltage]



[High Voltage]



Note: The condenser and chalk coil are not used in some areas. The M434 is only for 100V.